

 Cambium Networks Cambium Networks, Inc. 3800 Golf Road Schaumburg, IL 60008, U.S.A.	Document Number	FSB 9083
	Revision	000v001
FIELD SERVICE BULLETIN Update cnMaestro Cloud Managed Device Software by June 30, 2021 to Prevent Service Loss	Application	Global
	Effective Date	10 November 2020
	Expiry Date	N/A

FIELD SERVICE BULLETIN

BULLETIN TYPE		SEVERITY RECOMMENDATION	
X	Warranty Service		High – Perform immediately
	Informational	X	Medium – Perform at next scheduled maintenance
	Customer Specific		Low – Perform when system exhibits symptoms

SUBJECT: Update cnMaestro Cloud Managed Device Software by June 30, 2021 to Prevent Service Loss

Software/Configuration AFFECTED: All cnMatrix, cnPilot, Enterprise Wi-Fi 6, ePMP, PMP, and PTP devices managed by cnMaestro Cloud.

Symptom	On July 1, 2021 Cambium will update the certificate for cloud.cambiumnetworks.com to use a new Certificate Authority. All cnMaestro managed devices without the updated Root CA certificate will fail to connect to the cnMaestro Cloud service.
----------------	--

Recommendation/Resolution	<p>Customers must update their device firmware to at least the version listed below by June 30, 2021 to guarantee uninterrupted connectivity to cnMaestro Cloud. Devices not updated by June 30 will lose access to cnMaestro Cloud, and their firmware will require manual installation. This issue does not affect cnMaestro On-Premises.</p> <p>If you have questions or concerns please contact Cambium Technical Support at the following: https://www.cambiumnetworks.com/support/contact-support/</p> <p>Minimum Software Versions with New Root CA Certificates are listed in the table below.</p>
----------------------------------	--

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2012 Cambium Networks, Inc.



Cambium Networks

Cambium Networks, Inc.
3800 Golf Road
Schaumburg, IL 60008, U.S.A.

Document Number FSB 9083

Revision 000v001

FIELD SERVICE BULLETIN Update cnMaestro Cloud Managed Device Software by June 30, 2021 to Prevent Service Loss

Application Global

Effective Date 10 November 2020

Expiry Date N/A

Family	Model	Version
cnMatrix	cnMatrix EX2K	2.1-r5
cnPilot	cnPilot R200, R200P	4.6-R16
	cnPilot R201, R201P	4.6-R16
	cnPilot R190V, R190W	4.6-R16
	cnPilot e400/e500	3.11.4.1-r3
	cnPilot e410/e430w/e600	3.11.4.1-r3
	cnPilot R195P	4.7-R6
	cnPilot R195W	4.6-R16
	cnPilot e501S/e502S	3.11.4.1-r3
	cnPilot e700	3.11.4.1-r3
	cnPilot e425/e505	4.1-r3
	cnPilot e510	3.11.4.1-r3
cnRanger	Sierra 800	1.1-r3
	Tyndall 101	1.1-r3
cnReach	N500	5.2.18h
Enterprise Wi-Fi 6	XV3-8	6.1-r5
	XV2-2	6.1-r5
ePMP 1000 Hotspot	ePMP 1000 Hotspot	3.3.1.2-r1
ePMP	ePMP 1000, Force 180/200	4.5.0
	ePMP 2000	4.5.0
	ePMP Elevate XM/XW	4.5.0
	ePMP Force 190	4.5.0
	ePMP Force 300	4.5.0
	ePMP PTP 550	4.5.0
	ePMP MP 3000	4.5.0
	ePMP PTP 550 E	4.5.0
	ePMP Elevate SXGLITE5	4.5.0
	ePMP Elevate LHG5	4.5.0
	ePMP 3000	4.5.0
PMP	PMP 450i, PMP 450, PMP 450m, PMP 430 SM	20.0 Beta-6
	PTP 450, PTP 450i, PMP 450 Retro	20.0 Beta-6
	Micro-pop Omni/Sector	20.0 Beta-6
PTP	PTP 650	650-01-50
	PTP 670 (650 Emulation)	670-01-50, 670-03-12
	PTP 670, PTP 700	700-03-11

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2012 Cambium Networks, Inc.